## The Office of the Assistant Engineer Public Works Department Deomali

We have inspected the School Buildings (both Secondary and Higher Secondary) of the Ramakrishna Mission School, Narottam Nagar 792 129, Arunachal Pradesh.

The secondary section building is G+2 storied, built on RCC structure during 1978. The structural category of the building envisaged RCC flat roof at  $1^{\rm st}$  and  $2^{\rm nd}$  floor. The roof of the second floor is having CGI roofing on steel truss structure finished with false ceiling.

The Higher Secondary Section building is of RCC structure with CGI roofing on steel truss finished with false ceiling.

Both the buildings are well ventilated, have wide corridors, passages, adequate doors and windows, staircases etc., for easy movement. There are sufficient toilets. There is also arrangement for drinking water.

Both the school buildings are well maintained and structurally safe and sound.

09 November, 2016

Assistant Engineer

PWD Sub-Order PWD Sub-Order Deomail

Executive Engineer
Knonsa Division, PWD, A.P.
Khonsa